Next 2 Page(s) In Document Exempt

16/90402

SG1

B

ZCZC243

849/162025Z ZFF-3

17'53

XXXXX	SG1A	

SG1A PSEC	R E T 161	935Z CIT		· -	
SG1A IMMEDIATE	7] 1NFO: I	MMEDIATE		
	SG1A	. ×		į.	4

88722 .A

- B. FLASH REPORT AFTER PROCESSING
- C. TYPE 1
- D. F.
- E. THE FILM ARRIVED IN GOOD PHYSICAL CONDITION WITH UNDEREXPOSURE OF APPROX 1/2 STOP ON ALL FORWARD FRAMES, MEDIUM CONTRAST, GOOD RESOLUTION, WITH NORMAL METERING, AND OPERATIONAL RECORDING.

 THE CLOCK ON EVERY OTHER FORWARD FRAME IS IN THE IMAGE AREA. A SLIGHT WINUS DENSITY LINE DOWN CENTER OF AFT FRAMES. OVERLAP AND CLOCKS IN IMAGE AREA IN FRAMES 476-496. TIMUS DENSITY LINE ON FORWARD FRAMES OPPOSITE CLOCK EDGE ON LAST 3RD OF THE MISSION.


 TO P. S. E. C. R. E. T.

53





Next 26 Page(s) In Document Exempt

Approved For K (APP 69B00041R000700030017-1



Approved For Release 2003/12/19: CIA-RDP69B00041R000700030017-1





Next 10 Page(s) In Document Exempt